



Mailing: P.O. Box 1286
 Holland, MI 49424-1286
 Phone: 616.355.2970
 Fax: 616.355.2972
 www.dri-design.com

DATE: February 05, 2010

DESCRIPTION:

HORIZONTAL DEFLECTION JOINT

NOTE:

THE PANEL DEFLECTION JOINT MUST BE LOCATED ABOVE THE WALL DEFLECTION JOINT.

